



Phone: (816) 246-4500  
Fax: (816) 246-1452  
Web: [aeroexpress.com](http://aeroexpress.com)  
Email: [sales@aeroexpress.com](mailto:sales@aeroexpress.com)

## Aircraft Maintenance and Support Equipment

Rev. A (7/15)

### **RECOMMENDED SPARE PARTS FOR MALABAR MODEL 8939, 25 TON SINGLE STAGE HYDRAULIC AVIATION AXLE JACK**

The following spare parts are recommended and available upon request.

<b><u>Part No.</u></b>	<b><u>Description</u></b>	<b><u>Qty</u></b>
8939PK	Repair parts kit -----	1
442-072	Pump assembly -----	1
483-032	Air bleed valve -----	1
894219	Sticker, identification -----	1
883914	Sticker, max. capacity -----	1
883913	Sticker, air vent -----	1
75938	Sticker, CE -----	1
55994	Sticker, fluid -----	1



Phone: (816) 246-4500  
Fax: (816) 246-1452  
Web: [aeroexpress.com](http://aeroexpress.com)  
Email: [sales@aeroexpress.com](mailto:sales@aeroexpress.com)

## Aircraft Maintenance and Support Equipment

Rev. A (7/15)

### **REPAIR PARTS KIT LIST P/N 8939PKDOC FOR MALABAR MODEL 8939, 25 TON SINGLE STAGE HYDRAULIC AVIATION AXLE JACK**

Refer to owner's service manual for instructions.

<u>Part No.</u>	<u>Description</u>	<u>Qty</u>
893908	Wiper -----	1
55920-332	Back-up ring -----	1
55925-332	O-ring-----	1
55925-233	O-ring-----	1
371-015	Roll pin, 1/8 dia x 3/8 lg -----	1
373-027	Clevis pin, 5/16 dia x 1-1/8 usable length-----	3
372-032	Cotter ring -----	3